

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : City of Garland Landfill-Castle Drive
LOCATION : Garland
SITE NUMBER: TXD980626766
SURVEY DATE: 6 / 22 / 93 INSPECTED BY: STATE FIT TAT OTHER: Fluor Daniel
LABORATORY : CLP EPA OTHER

RECEIVED FROM: Betty Williamson DATE RECEIVED: 10 / 22 / 93

SAMPLE TYPE(s):

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

N	Locate Drinking Water Sources
N (Re)Sampling Requested	Y Keep Site Active ("N"=No Further Action)
N Further Action is URGENT	Y Concur with Report Recommendations

SUMMARY: This site is a part of the City of Garland's municipal landfill. I agree with the recommendation that a final disposition decision for this site not be made until all the analytical data has been reviewed.

Concurrence:

R. Warren Morris 11/19/93

Len Pader
ENGINEER/REVIEWER

11/15/93

9028457

